Preservation Planning and Tools: Charlestown

CHARLESTOWN PRESERVATION SOCIETY

PROTECT HISTORIC CHARLESTOWN COMMITTEE PRESENTATION

01/2021

Topics

Community-Level Historic Preservation Planning

- 1) Identification
- 2) Evaluation
- 3) Protection



Topics

Community-Level Historic Preservation Planning

- 1) Identification
- 2) Evaluation
- 3) Protection



Why Conduct an Architecture/Historic Resources Survey?

To identify and document historic resources


- Serves to guide planning policy on significance
- Provides basis for determining National Register eligibility
- Assists with preserving historic assets through landmarking, creation of historic/conservation districts, Article 85 (demolition delay review).
- Educational purposes


You can survey... Areas,






You can survey... Buildings,





You can survey... Buildings,






You can survey... Objects,








You can survey... Burying Grounds,







You can survey... Parks and Landscapes,





... and more!





Massachusetts Cultural
Resource Information System
(MACRIS) Forms

Maintained by Mass. Historical. Commission (MHC)

Massachusetts Cultural Resource Information System

Scanned Record Cover Page

Inventory No: BOS.4226

Historic Name: Burbank, Silas and Son Varnish Factory

Common Name: Wright - Whittemore Tanning Oil Company

Address: 62 Alford St Arlington Ave

City/Town: Boston

Village/Neighborhood: Charlestown; Charlestown West; Charlestown Neck; Sullivan Square

...

Local No: C700 Year Constructed: c 1880

Architect(s):

Architectural Style(s): Second Empire

Use(s): Factory Other; Other Manufacturing

Significance: Architecture; Industry

Area(s): BOS.RM: Charlestown Mystic River Industrial Area

Designation(s):

Building Materials(s):

Roof: Slate

Wall: Brick; Concrete Cinderblock; Granite; Sheet Metal;

Stone, Cut

Foundation: Stone, Cut



Massachusetts Cultural Resource Information System (MACRIS) Forms

Maintained by Mass. Historical. Commission (MHC)


Mostly intensive-level survey forms

- Architectural Significance
- Historical Significance
 - Ownership
 - Builder/Architect
 - Businesses, events, etc.
- Preservation Considerations

V C	
1.10	ADDRESS 62 Alford St. COR. Arlington Ave.
	NAME Silas Burbank and Son Varnish Factory/Whittemore Wr present original Co.
	MAP No. 30N-11E SUB AREA
	c. 1880, enlarged c.1890 Atlases
A STATE OF THE STA	source
mell Lating	ITECT
THE REAL PROPERTY AND ADDRESS OF THE PARTY AND	
MAN OILS	DER source
	Silas Burbank, Charles G. Burbank
	original present
	PHUIOGRAPHS C-town4.5/2,3,4,5.86
	cupola dormers 10-dormers, rear wail dormers removed from main facade
mallootu	
ATERIALS (Frame) clapboards	shingles stucco asphalt asbestos alum/vinyl stoneconcrete iron/steel/alum.
TERIALS (Frame) clapboards (Other) brick HEF DESCRIPTION Rectangular, nsard roof. 18-bay main fac- rfaces pierced by segmental icks. Windows contain vario- rthy is early-mid 20th c. p. dewalls. Roof slates are mo-	
TERIALS (Frame) clapboards (Other) brick HEF DESCRIPTION Rectangular nsard roof. 18-bay main fact rfaces pierced by segmental icks. Windows contain varior rthy is early-mid 20th c. pi dewalls. Roof slates are mo: TERIOR ALTERATION minor	stoneconcrete iron/steel/alum. Mansard factory building rises 3-stories to straight-sided ade, 2-bay sidewalls. Characterized by planar brickwork headed windows w/lintels composed of two rows of header us sash configurations9/6, 2/2, 1/1 etc. Particularly note-ainted advertising on Arlington St., Main St. and Mystic River stly intact. Dormers on Arlington Ave. side exhibit distinctive* moderate drastic Main facade dormers no longer intact Rear ell greatly reduced
TERIALS (Frame) clapboards (Other) brick MEF DESCRIPTION Rectangular nearly roof. 18-bay main factoriscs. Windows contain various ricks. Windows contain various early-mid 20th c. prodewalls. Roof slates are montering and alternation minor on the contain poor minor of the contain poor minor of the contain poor minor of the contain poor minor minor of the contain poor minor minor of the contain poor minor	stoneconcrete iron/steel/alum. Mansard factory building rises 3-stories to straight-sided ade, 2-bay sidewalls. Characterized by planar brickwork headed windows w/lintels composed of two rows of header us sash configurations9/6, 2/2, 1/1 etc. Particularly note-ainted advertising on Arlington St., Main St. and Mystic River stly intact. Dormers on Arlington Ave. side exhibit distinctive* moderate drastic Main facade dormers no longer intact Rear ell greatly reduced
TERIALS (Frame) clapboards (Other) brick HEF DESCRIPTION Rectangular nsard roof. 18-bay main fact reaces pierced by segmental icks. Windows contain varior rthy is early-mid 20th c. pa dewalls. Roof slates are mon TERIOR ALTERATION minor ONDITION good fair poor TEWORTHY SITE CHARACTERIST	. Mansard factory building rises 3-stories to straight-sided ade, 2-bay sidewalls. Characterized by planar brickwork headed windows w/lintels composed of two rows of header us sash configurations9/6, 2/2, 1/1 etc. Particularly note-ainted advertising on Arlington St., Main St. and Mystic River stly intact. Dormers on Arlington Ave. side exhibit distinctive moderate drastic Main facade dormers no longer intact Rear ell greatly reduced LOT AREA 14,600 sq. feet ICS Situated near Mystic River, across from Schraffts building
TERIALS (Frame) clapboards (Other) brick MEF DESCRIPTION Rectangular neard roof. 18-bay main factoriaces pierced by segmental icks. Windows contain varior ricks. Windows contain varior rthy is early-mid 20th c. prodewalls. Roof slates are monterior allowed the recommendation of the rectangle o	. Mansard factory building rises 3-stories to straight-sided ade, 2-bay sidewalls. Characterized by planar brickwork headed windows w/lintels composed of two rows of header us sash configurations9/6, 2/2, 1/1 etc. Particularly note-ainted advertising on Arlington St., Main St. and Mystic River stly intact. Dormers on Arlington Ave. side exhibit distinctive moderate drastic Main facade dormers no longer intact Rear ell greatly reduced LOT AREA 14,600 sq. feet

Charlestown Preservation

Society Survey



Topics

Community-Level Historic Preservation Planning

- 1) Identification
- 2) Evaluation
- 3) Protection



Step 2: Evaluation


Evaluate surveyed resources based on historical context and architectural integrity

- Significance: Importance of a site based on architecture, historic events, people, archaeological potential, etc.
- Context: patterns, themes, or trends in history by which a property or site is understood and its significance within history is made clear.
- Integrity: the degree to which a site or building's original design and physical composition is evident and intact.

Significance: EMF Building (1920/1948), 116 Brookline Street, Cambridge



Significance: EMF Building (1920/1948), 116 Brookline Street, Cambridge






Significance: EMF Building (1920/1948), 116 Brookline Street, Cambridge



Example: Apthorp House (1760), Cambridge






Context: Poor

Integrity: Great

Example: East Cambridge House (1871), Cambridge



Context: Good

Integrity: Poor

Topics

Community-Level Historic Preservation Planning

- 1) Identification
- 2) Evaluation
- 3) Protection



Step 3: Protection

If properties are deemed to be historically significant and retain reasonable historic context and architectural integrity:


- Action can be taken to protect the building, area, structure, object, etc.
 - Proactive Tools
 - National Register (Individually or District)
 - Local Historic District/Landmark (Individually or District)
 - Local Architectural Conservation District (District)
 - Reactive Tools
 - Demolition Delay (Individually)

Step 3: Protection

National Register of Historic Places:

- The official list of country's historic buildings, districts, sites, worthy of preservation.
- Federal program, administered at the state level through Massachusetts Historical Commission.
- Planning tool that protects properties from adverse effects of Federal- or State-funded projects and activities (Section 106 Review).
- Provides no protections from owners altering own properties.
- Eligible for tax credits for qualified historic rehabilitation projects, mostly for large projects.

Step 3: Protection National Register of Historic Places: Charlestown



Step 3: Protection National Register of Historic Places: Charlestown

Districts:


- 1. <u>Boston Naval Shipyard</u> (1966)
- 2. Hoosac Stores 1 & 2-Hoosac Stores 3 (1985)
 *Hoosac Stores 3, demolished in 2000
- 3. Monument Square Historic District (1987)
- 4. <u>Terminal Storage Warehouse District</u> (2012)
- 5. Town Hill District (1973)

Individual:

- 1. Francis B. Austin House (1988)
- 2. <u>Bunker Hill Monument (1966)</u>
- 3. Bunker Hill School (1987)
- 4. <u>Charlestown Heights-Doherty Playground</u> (1998)
- 5. Phipps Street Burying Ground (1974)
- 6. Roughan Hall (1982)
- 7. USS Cassin Young (destroyer) (1986)
- 8. <u>U.S.S. Constitution</u> (1966)

Local Landmark: Individual building or site protected by Boston Landmarks Commission.

- Study Report, catered to individual building
 - Design standards and criteria covers:
 - Masonry
 - Windows
 - Materials
 - Lighting and signage
 - Etc.



Historic Districts: Strictest form of historic protection available at neighborhood-level

More restrictive


- All publicly visible alterations require review and approval by local historic district commission/staff
- Regulates everything down to appropriateness of paint color
- Examples: Back Bay Architectural District, Beacon Hill Architectural District



Architectural Conservation District: More flexible review criteria than Local Historic Districts

- Design criteria catered to neighborhood preservation goals
 - Study process identified unique neighborhood characteristics and conservation goals
 - Allows specific alterations to be reviewed staff level
 - Replacement in-kind, upgrade in materials, appropriate windows, no review on paint, etc.
 - Examples: Aberdeen Architectural Conservation District





https://www.boston.gov/departments/landmarks-commission/map-boston-historic-landmarks-and-districts#map--317711

Districts:

- Baldwin Street Architectural Conservation District
- Town Hill Landmark District (Pending)

Individual:

- 1. Austin Block
- 2. Charlestown Savings Bank
- 3. Edward Everett House
- 4. Great House Archaeological Site (City Square Park)
- 5. The Ropewalk (Pending)











Step 3: Protection

Article 85 Demolition Delay:

- Provides a predictable process for reviewing requests to demolish buildings in Boston
- Reactionary planning tool
- What buildings are subject to Article 85 review?
 - All buildings located in either the Downtown or Harborpark
 - All buildings at least fifty years of age
 - All buildings located in a Neighborhood Design Overlay District
 - Charlestown Neighborhood Design Overlay District

Step 3: Protection

Article 85 Demolition Delay Process:

- 1) Complete application submitted to Boston Landmaks Commission
- 2) Posted online, 10 days for determination of "significant" or "not significant", based on Article_85-5.3 definition
 - If "not significant", demolition permit granted.
- 3) If deemed significant, a public hearing scheduled within 30 days before BLC.
 - Applicant is required to hold a community meeting to abutters presenting alternatives to demolition, prior to BLC hearing.
- 4) At BLC hearing, Commission <u>may</u> decide to institute a demolition delay to analyze alternatives for a "win-win" with neighborhood.
 - 90-day delay
 - Cambridge Demolition Delay= 12 months
- 5) At end of 90 days, delay may expire, or landmark study may be undertaken (not common)

Questions?